Office of the Asst.Divisional Officer, Fire & Rescue Services, Malappuram

Dated: 13/01/2017

NO OBJECTION CERTIFICATE

Certified that I have inspected the laboratory room of the School building, named ST.Francis School, Vaniyambalam(PO), Malappuram located in Wandoor Panchayath, ward No.7 in Re Survery No.336/3,5 335/1234 of Wandoor Village, Nilambur Taluk of Malappuram District, LPG cylinder are used for Laboratory Purpose, on where three 13/01/2017 in fire safety point of view and found that the necessary first aid fire fighting equipments are installed in the laboratory of the building which are in good working condition.

Hence this department has no objection for the functioning of laboratory in above said school.

DIVI: OFFICE

Copy to

Manager

ST.Francis School,

Vaniyambalam(PO),

Malappuram

St. Francis School Kuttumunda Vanlyambalam P.O Malappuram Dt., 679339

Asst.Divisional Officer, Fire & Rescue Services,

Malappuram.

St. Francis School Kuttumunda Vaniyambalam P.O. Malappuram Dt., - 679339