

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

Name of the School : ST FRANCIS SCHOOL, VANIYAMBALAM

1. Name of the Officer : SHAHRUKH K.V
2. Location : WANDOOD
3. Period for which the certificate is issued : 2026-2027
4. Types of building : RCC Building
5. Nature of defect if any :
 - a) Foundation and basement : NIL
 - b) Superstructure : NIL
 - c) Doors and windows : NIL
 - d) Wood work wrought and put up : NIL
 - e) Roof : NIL
 - f) Flooring : NIL
 - g) Miscellaneous (Cracks if any) : NIL
6. Any Major defects notices which will render the building unsafe in any manner : No defects noticed
7. Whether maintenance works have been done properly : YES
8. Whether the structure is sound or not for conducting classes : Yes, fit for conducting classes under normal weather conditions during 2026-2027

Note:- 1. The stability of the structure should be examined also with reference to location altitude intensity of wind exposure or flood etc.
2. Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.
3. the electrical wiring in the school building. shall be examined by a approved/licensed wireman within one month
4. the headmaster/ applicant should obtain all the relevant NOCs from the various department as per the circular No M3/347/2019- health dated 09/11/2025 .

CERTIFICATE

Certified that the School was inspected by me on 29/05/2026
and found to be fit / ~~unfit~~ to conduct classes for the period 2026-2027
for the reason stated above.

Place: Wandoor
Date: 29/05/2026

(Seal)

Assistant Engineer

Remarks:

1. Steps to regularize unauthorized construction if any should be taken within two months.

ST. FRANCIS SCHOOL , VANIYAMBALAM

BLOCK 1: RCC Building


- GF- 9.00 x 6.00 x 3.60 m – 5 Class Rooms
8.00 x 5.00 x 3.60 m – 1 Class Room
8.00 x 5.00 x 3.60 m – 1 Staff Room
6.97 x 3.65 x 3.60 m – 1 Store Room
- FF- 9.00 x 6.00 x 3.60 m – 5 Class Rooms
8.00 x 5.00 x 3.60 m – 1 Class Room
8.00 x 5.00 x 3.60 m – 1 Staff Room
6.97 x 3.65 x 3.60 m – 1 Store Room
- SF – 9.00 x 6.00 x 3.60 m – 3 Class Rooms
8.00 x 5.00 x 3.60 m – 1 Class Room

BLOCK 2: RCC Building

- GF 12.00 x 6.00 x 3.60 m – 2 Lab
8.96 x 6.00 x 3.60 m- 1 Lab
8.40 x 7.60 x 3.60 m – 1 Lab
- FF- 12.00 x 6.00 x 3.60 m – 2 Lab
8.96 x 6.00 x 3.60 m- 1 Lab
8.40 x 7.60 x 3.60 m – 1 Lab
- SF – 8.40 x 20.60 x 3.60 m – Library

BLOCK 3: RCC Building

- GF 9.00 x 6.00 x 3.60 m – 5 Class Rooms
8.00 x 5.00 x 3.60 m – 1 Class Room
8.00 x 5.00 x 3.60 m – 1 Staff Room
6.97 x 3.65 x 3.60 m – 1 Store Room
- FF- 9.00 x 6.00 x 3.60 m – 5 Class Rooms
8.00 x 5.00 x 3.60 m – 1 Class Room
8.00 x 5.00 x 3.60 m – 1 Staff Room
6.97 x 3.65 x 3.60 m – 1 Store Room
- SF – 9.00 x 6.00 x 3.60 m – 3 Class Rooms
8.00 x 5.00 x 3.60 m – 1 Class Room


SHAHEER K V
Assistant Engineer
LID & EW Section
Wandoor Grama Panchayat
PEN : 946689

